



Inventor: William D. WILBER, et al.  
Appl. No.: 09/987,376 Group Art Unit: 2817  
UNABLE TRIPLE-MODE MONO-BLOCK  
FILTER ASSEMBLY  
SM, PLLC Ref. No.: A8241  
SM, PLLC Phone No.: 202-293-7060  
Sheet 1 of 16




FIG. 1a




FIG. 1b




FIG. 2



Inventor: William D. WILBER, et al.  
Appl. No.: 09/987,376 Group Art Unit: 2817  
UNABLE TRIPLE-MODE MONO-BLOCK  
FILTER ASSEMBLY  
SM, PLLC Ref. No.: A8241  
SM, PLLC Phone No.: 202-293-7060  
Sheet 3 of 16




FIG. 3a




FIG. 3b

Inventor: William D. WILBER, et al.  
Sln. No.: 09/987,376 Group Art Unit: 2817  
UNABLE TRIPLE-MODE MONO-BLOCK  
FILTER ASSEMBLY  
SM, PLLC Ref. No.: A8241  
SM, PLLC Phone No.: 202-293-7060  
Sheet 4 of 16




FIG. 4

Inventor: William D. WILBER, et al.  
In. No.: 09/987,376 Group Art Unit: 2817  
UNABLE TRIPLE-MODE MONO-BLOCK  
FILTER ASSEMBLY  
SM, PLLC Ref. No.: A8241  
SM, PLLC Phone No.: 202-293-7060  
Sheet 5 of 16




FIG. 5

Inventor: William D. WILBER, et al.  
Apn. No.: 09/987,376 Group Art Unit: 2817  
UNABLE TRIPLE-MODE MONO-BLOCK  
FILTER ASSEMBLY  
SM, PLLC Ref. No.: A8241  
SM, PLLC Phone No.: 202-293-7060  
Sheet 6 of 16




FIG. 6

Inventor: William D. WILBER, et al.  
Apn. No.: 09/987,376 Group Art Unit: 2817  
PUNABLE TRIPLE-MODE MONO-BLOCK  
FILTER ASSEMBLY  
SM, PLLC Ref. No.: A8241  
SM, PLLC Phone No.: 202-293-7060  
Sheet 7 of 16




FIG. 7

Inventor: William D. WILBER, et al.  
Sln. No.: 09/987,376 Group Art Unit: 2817  
UNABLE TRIPLE-MODE MONO-BLOCK  
FILTER ASSEMBLY  
SM, PLLC Ref. No.: A8241  
SM, PLLC Phone No.: 202-293-7060  
Sheet 8 of 16




FIG. 8a




FIG. 8b




FIG. 9

Inventor: William D. WILBER, et al.  
Appl. No.: 09/987,376 Group Art Unit: 2817  
UNABLE TRIPLE-MODE MONO-BLOCK  
FILTER ASSEMBLY  
SM, PLLC Ref. No.: A8241  
SM, PLLC Phone No.: 202-293-7060  
Sheet 10 of 16




FIG. 10a




FIG. 10b



Inventor: William D. WILBER, et al.  
Sln. No.: 09/987,376 Group Art Unit: 2817  
UNABLE TRIPLE-MODE MONO-BLOCK  
FILTER ASSEMBLY  
SM, PLLC Ref. No.: A8241  
SM, PLLC Phone No.: 202-293-7060  
Sheet 11 of 16




FIG. 11d




FIG. 11c




FIG. 11b




FIG. 11a



Inventor: William D. WILBER, et al.  
Apn. No.: 09/987,376 Group Art Unit: 2817  
UNABLE TRIPLE-MODE MONO-BLOCK  
FILTER ASSEMBLY  
SM, PLLC Ref. No.: A8241  
SM, PLLC Phone No.: 202-293-7060  
Sheet 12 of 16




FIG. 12a




FIG. 12b



Inventor: William D. WILBER, et al.  
Apn. No.: 09/987,376 Group Art Unit: 2817  
UNABLE TRIPLE-MODE MONO-BLOCK  
FILTER ASSEMBLY  
SM, PLLC Ref. No.: A8241  
SM, PLLC Phone No.: 202-293-7060  
Sheet 13 of 16




FIG. 13




FIG. 14a




FIG. 14b




FIG. 14c




FIG. 15